

Wire Inch to Gage Chart

Gauge	American Brown Copper	Wash Moen	Imperial S.W.G.
0000000			0.50000
000000	0.58000	0.49000	0.46400
00000	0.51650	0.41650	0.43200
0000	0.46000	0.39380	0.40000
000	0.40960	0.36250	0.37200
00	0.36480	0.33100	0.34800
0	0.32490	0.30650	0.32400
1	0.28930	0.28300	0.30000
2	0.25760	0.26250	0.27600
3	0.22940	0.24370	0.25200
4	0.20430	0.22530	0.23200
5	0.18190	0.20700	0.21200
6	0.16200	0.19200	0.19200
7	0.14430	0.17700	0.17600
8	0.12850	0.16200	0.16000
9	0.11440	0.14830	0.14400
10	0.10190	0.13500	0.12800
11	0.09070	0.12050	0.11600
12	0.08080	0.10550	0.10400
13	0.07200	0.09150	0.09200
14	0.06410	0.08000	0.08000
15	0.05710	0.07200	0.07200
16	0.05080	0.06250	0.06400
17	0.04530	0.05400	0.05600
18	0.04030	0.04750	0.04800
19	0.03590	0.04100	0.04000
20	0.03200	0.03480	0.03600
21	0.02850	0.03170	0.03200
22	0.02540	0.02860	0.02800
23	0.02260	0.02580	0.02400
24	0.02010	0.02300	0.02200
25	0.01790	0.02040	0.02000
26	0.01590	0.01810	0.01800
27	0.01420	0.01730	0.01640
28	0.01260	0.01620	0.01480
29	0.01130	0.01500	0.01360
30	0.01000	0.01400	0.01240